

# MOISTURE MONITOR:

## Moisture Monitor

- Monitors moisture level inside dry box in dew point and PPM- parts per million
- Automatic software calibration
- Sensor with fixed output zero – no adjustment required
- High capacitance sensor uses 50 or 60 HZ excitation, no amplification
- Includes: one sensor probe
- Interfaces with Polaris Welding systems and shows error codes on weld controller
- If moisture exceeds a pre-set value, the Venus IV or Accu-Weld will not weld
- Power requirements: 100/120V, 50/60 Hz, less than 30 watts
- Signal Output: Standard 4-20mA
- One year warranty
- Made in USA

